

Durno, Mark

From: Durno, Mark
Sent: Wednesday, August 16, 2017 10:08 AM
To: Deltoral, Miguel
Subject: FW: Test Results
Attachments: UA370 [REDACTED] 1708227 Report.pdf

FYI – the home we were discussing last week (with the lead fishing sinkers in her bathtub faucet).... I believe that she has a galvanized service line.

md

Mark Durno

Homeland Security Advisor
Emergency Response Branch
U.S. Environmental Protection Agency
25063 Center Ridge Road
Westlake, OH 44145
440-250-1743

From: [REDACTED]
Sent: Wednesday, August 16, 2017 9:33 AM
To: George Krisztian <krisztiang@michigan.gov>; Durno, Mark <durno.mark@epa.gov>
Subject: FW: Test Results

From: [REDACTED]
Date: Wednesday, August 16, 2017 at 9:31 AM
To: [REDACTED]
Cc: [REDACTED]
Subject: Test Results

[REDACTED]
Attached are your recent testing results as completed by [REDACTED] and [REDACTED] from the UA370 (Plumbers' Union).

A summary is as follows:

1. Shower: Non-detect for lead. Note this location is outside of any current regulatory requirements.
2. Kitchen Sink: 51 ppb for lead.
3. UA370 Sink (as a control): Non-detect for lead.
4. Meter: 100 ppb for lead. Note this location is outside of any current regulatory requirements.
5. Water Heater: 210 ppb for lead. Note this location is outside of any current regulatory requirements.

Best Regards,

[REDACTED]
[REDACTED]

